	Approved For Release 2004/07/08 : CIA-RDP80-00810A00220023002 F3 LD 9	83
S.	CLASSIFICATION 25X1 25X1	
COUNTRY_	t Greeny REPORT	
TOPICOra	anienburg Airfield	digmakat g mijayanga misk
EVALUATION_	25X1 PLACE OBTAINED 25X1	2-10-10-10-10-10-10-10-10-10-10-10-10-10-
DATE OF CONT	TENT_ 18 June to 25 July 1953	
DATE OBTAINE	05V4 32 tomat 3052	
REFERENCES_		galanter, d'antiès si
PAGES 2	ENCLOSURES (No. & TYPE)	-
REMARKS		
		Banda Jat - Miles F
25X1		
25X1	. The following observations were made at Oranienburg airfield between 18 J and 21 July 1953:	une
	18 and 19 June. A truck camouflaged by bushes and an emplaced gun were observed on both sides at the northern end of the runway. On 18 June, the Soviet sentries armed with carbines were observed lying in the grass at the northeastern exit of Leegebruch.	ree
	2 July. On the northern edge of the field, cement was being unloaded fr seven boxcars onto trucks, which subsequently moved to the airfield. In center of the field, there were about 10 additional boxcars on which wo was done. Clouds of dust rose from this area at the time.	the
	10 July. The roadbed of the new railway leading toward the fuel dump in northern section of the field had been filled with ballast and the rail ties had also been laid.	the
25X1	Early July. every day between the hours of 4 p.m. a 5 p.m., the workers changed shifts. Work apparently also continued at ni as the field was illuminated by searchlights. The workers who left the f at about 4 p.m. went to the southern section of the Weisse Stadt settlem On 4 July, the shrapnelproof aircraft revetments	ight, Tield ment.
25X1	apparently been painted a green-brown camouflage color.	
	21 July. Work was under way on the north-south runway.	
2.	After 29 June, work at the field again continued with the previous strength of about 1,200 men. However, individual workers had been transferred to Leipzig area where dwellings were to be constructed. Repair work had to done on the runway, which was in poor condition. Between 7 and 18 July, work was under way on additional shrapnelproof aircraft revetments. The completed revetments were painted with a camouflage paint in green, yell	the be no
	25X1	-
	CrCbrd	
· dept	CLASSIFICATION	

25X1

	25X1
4	3
	2 -
	brown and red. For testing purposes, the runway was also provided with a coat of dark camouflage paint. A construction site was being surveyed near
25X1	the spur track, located about 100 meters northeast of the hangar. Construction work at the field was nearing completion. One cement storage shed at the landing field had already been removed.
3	the Soviet supervisor at Oranienburg airfield was
25X1	Romanenko (fnu) who interceded in favor of the German workers during the disturbances. On 17 June, the German workers were unable to proceed toward
25X1	Berlin and had to return to their quarters which, in the meanwhile, had been occupied by Soviet troops. Romanenko managed it so that the troops withdrew without making arrests.
25X1 25X1	withdrew without making arrests.
4	. Up to 5 July, concreting work on the taxiway was completed. This work continued on the hardstands and construction work was also done on aircraft
	revetments. On 13 July, 22 shrapnelproof aircraft revetments were consisted and provided with a coat of camouflage paint. Concreting work could not continue because of a lack of cement. One cement storage shed had already been removed in early July. Some workers were transferred to other construction sites.
25X1 5	on 25 July a party was given for the workers upon completion of the main construction work. A portion of the construction workers had already been transferred.
6	. Some of the shraphelproof aircraft revetments in the southern section of the field near Wilhelmsthal estate had by 12 July been covered with sand. The concrete slabs of the revetments were provided with a coat of camouflage paint. 2
25X1	Comment. These are protective measures which were taken during the disturbances between 17 and 20 June 1953.
25X1 [25X1	Comment. The present report contains details on the previously reported improvement work at Oranienburg airfield. Noteworthy is the information on the poor condition of the runway, which confirms previous observations
25X1	Soviet supervisor Romanenko was previously reported as holding the rank of Lieutenant Colonel. It is
25X1	also noteworthy that the shrapnelproof aircraft revetments and the runway are being provided with a coat of camouflage paint. In this connection, reference is made to information in November 1952, stated that
25X1	is made to information
	25X1
	SECRET